

From: ["Wallingford, Jonni B." <wallingfordjb@cdmsmith.com>](mailto:Wallingford, Jonni B. <wallingfordjb@cdmsmith.com>)

To: ["Zhen, Davis" <Zhen.Davis@epa.gov>](mailto:Zhen, Davis <Zhen.Davis@epa.gov>)

["Sheldrake, Sean" <sheldrake.sean@epa.gov>](mailto:Sheldrake, Sean <sheldrake.sean@epa.gov>)

CC: younghs@cdmsmith.com

["Scott Coffey" <coffeyse@cdmsmith.com>](mailto:Scott Coffey <coffeyse@cdmsmith.com>)

["Vickstrom, Kyle E." <vickstromke@cdmsmith.com>](mailto:Vickstrom, Kyle E. <vickstromke@cdmsmith.com>)

Date: 8/22/2018 5:48:24 PM

Subject: Surface Water Sampling

Attachments: [IMG_20180822_172807534_HDR.jpg](#)

[IMG_20180822_172823339_HDR.jpg](#)

[IMG_20180822_172839992_HDR.jpg](#)

[IMG_20180822_172853931_HDR.jpg](#)

[IMG_20180822_172904500.jpg](#)

Good evening,

The Tieton is currently sampling at 3NAV. The Pre-RD has group has sampled at 3 target sites total; 3E, 3W and 3NAV, for a total of 8 different depths for the transect, and is currently sampling their last depth for the day (3ft). Included are photos of the of the site location 3NAV, and the pump during sampling operation.

Photo 1: site location 3NAV (RM 4) looking SE

Photo 2: site location 3NAV looking SW

Photo 3: Location 3NAV facing NE, Pre-RD recording data

Photo 4: Gravity PR2900 sampling at last depth (3ft)

Photo 5: gauge is monitored, filters are changed as gauge approaches 15psi

Get Outlook for Android<<https://aka.ms/ghei36>>